

East Central Railway

Office of the
General Manager (S&T)
Hajipur

No. ECR/S&T/Sig/Policy/200/Pt.IV 1029

Date: 29.05.2018

Sr.DSTEs
DHN, DNR, MGS, SEE, SPJ
East Central Railway**Sub: Damage of signal post ladder & signal unit fallen down by open door of wagons at Mahwal station in SPJ Divn. on 17.05.2018.****Ref:** Addendum & Corrigendum Slip No. 1 circulated vide AM (Signal) letter No. 2005/SIG/SEM/11, Dtd.-05.01.2006.

On 17.05.2018 ladder of Dn. Starter Signal No. 5 of Mahwal station got damaged & Signal unit fallen down due to hitting by open door of wagon nos. 33131012826 NCR & 33101099307 ECR of Train No. UP BCNHL. In the MFP-NKE-VKNR section, such type of cases occurred several times.

In view of above, divisions are advised to adopt colour scheme according to item no. 1.0 (c) of Railway Board letter under reference for indicating the implantation from nearest centre line of track.

List of signals which implantation is less than 2.36 meter should be send to this office with a copy to concerned divisional officer with an advice to take all necessary precaution to ensure closer of doors of wagons to avoid such incidences in future.

DA: As above.(S.R.Meena)
CSE

for GM (S&T)/ECR/HJP

Copy to: (i) CRSE/Freight/ECR for information & n/a please.