

East Central Railway

Office of the
General Manager
(S&T)ajipur

No. ECR/S&T/Sig/Policy/200/Pt.IV

1396

Date: 09.10.2018

Divisional Railway Manager
DHN, DNR, MGS, SEE, SPJ
East Central Railway

Sub: Provision of Axle counter on bridges along with track circuit.

Ref: RB L/No. 2017/Safety(A&R)/19/3 dtd. 09.04.2018.

It has been observed that several time Track circuits on bridge fails due to damaged insulation of clit bolt.

To improve reliability of Track Circuit, it is advised to provide Axle counter along with Track Circuit.

For monitoring the functioning of both Axle counter and track circuit separate indication in maintainer room should also be provided and no change in required on SMs panel.

This has approval of PCSTE/ECR.

DA:- As above.


(M.K. Srivastava)
Chief Signal Engineer
for GM (S&T)/ECR/HJP

Copy to: Sr.DSTE/DHN, DNR, MGS, SEE, SPJ for information and n/a.