

## **RED BULLETIN**

**No. ECR/Safety/Red Bulletin –Dec-21-22**

Date: 07.01.2022

**(1) Major irregularities noticed during inspections: -**

1. Goods guards in the SPJ division have been provided Pressure Gauges but adaptors have not been provided. As a result they are not being used. This is a safety item. Adaptors should be arranged at the earliest.
2. During inspection of west side FOB at Samastipur station, it was noticed that almost all MS protection sheets for OHE provided on FOBs are misaligned on the east side and missing on the west side.
3. During inspection, it is found that despite beginning of cold weather, patrolling was not started in SMI-RXL and SMI-MFP section. Concerned PWI told that there are shortages of manpower. It is safety issue. Action should be taken at the earliest in this regard.

**2. All Train Accident Analysis from April -21 to Nov-21- Division- wise position.**

| Type                     | DHN | DNR | DDU | SEE | SPJ | TOTAL |
|--------------------------|-----|-----|-----|-----|-----|-------|
| Collision                | 00  | 00  | 00  | 00  | 00  | 00    |
| Derailment               | 05  | 03  | 06  | 00  | 02  | 16    |
| L-Xing ( Manned)         | 00  | 00  | 00  | 00  | 00  | 00    |
| L-Xing ( Un-Manned)      | 00  | 00  | 00  | 00  | 00  | 00    |
| Fire in Trains           | 00  | 00  | 00  | 00  | 00  | 00    |
| Misc.<br>I.SPAD          | 00  | 01  | 01  | 00  | 01  | 03    |
| II.Breach of Block Rules | 00  | 00  | 00  | 00  | 00  | 00    |
| III. Averted Collision   | 00  | 00  | 00  | 00  | 00  | 00    |
| Unusual                  | 01  | 00  | 00  | 01  | 00  | 02    |
| Total                    | 06  | 04  | 07  | 01  | 03  | 21    |

**All Accident during Dec- 2021- 02**

**3. Items requiring special attention in Jan- 2021**

**General**

- (i) Co –ordination in loading of Brake Van equipments.

**Operating**

- (i) Surprise check regarding observance of rule while passing IBS signal at 'ON'.
- (ii) Special checks regarding availability of Safety equipments as per SWR.

**Personnel**

- (i) Ensure immediate sparing of staff for initial training centre.

**Mechanical**

- (i) Ensure Zero defect & most change items during 'IOH' of coaches.
- (ii) To Check and ensure that proper maintenance of equipments in pantry car are done and all necessary Certificates are available in Pantry Car.

**Electrical**

- (i) Surprise checks in running rooms regarding use of Mobile phone while taking rest.
- (ii) Ensure that all electrical wiring/ appliance are in proper conditions in Pantry Car to avoid any fire incidence.

## Engineering

- (i) Cold weather Patrolling – Launching of intensive cold weather patrolling when temperature is less than as specified in IRPWM.
- (ii) Lubrication of Curves, Point and crossing and Pendrol clips.

**S & T**

- (i) Checking of retro-reflective Strips is provided at L.C gates (All Spl., A&B) & Distant Signal.
- (ii) To check effectiveness of approach locking and track locking.

## Security

- (i) Patrolling of track in sabotage prone area.

## Commercial

- (i) Thorough checking to ensure complete unloading at destination.

**SUNIL KUMAR**

Digitally signed by **SUNIL KUMAR**  
DN: cn=Dr. INDIAN RAILWAY,  
ou=INDIAN RAILWAY,  
postalCode=844101, st=Uttar,  
2.5.4.20=f7c505c5193844648b0b0d6061  
8c7b11894b4c0271226b7f9ac79e6f7e6f6  
51d  
serialNumber=b79946747c1c705ec2c5  
7c2a4c0501c7404d4f715202c6a  
2aadb981a, cn=SUNIL KUMAR  
Date: 2022.01.07 15:58:14 +05'30'

**(Sunil Kumar)**

**Dy. CSO/ Traffic**

## East Central Railway, Hajipur

1. All DRMs/Sr. DSO- For information & distribution to all Branch Officers for n/a.
2. Principal, ZRTI/ MFP& BLI- For information & wide publicity amongst trainees.
3. Safety Camp/ DHN.