

East Central Railway

**श्री विजय कुमार, प्रधान मुख्य सामग्री प्रबंधक/पूमरे/हाजीपुर द्वारा दिनांक-12.12.2025 को टीआरएस
डिपो/समस्तीपुर का किये गये निरीक्षण का निरीक्षण रिपोर्ट**

Inspection Note No.07/2025 dated: 23.12.2025

Officers/Officials Present: -	
Shri Gaurav Kumar Singh	Sr.DMM/SPJ
Shri Arvind Kumar	Sr.DME (Dsl)/SPJ
Sri Jitesh Kumar Mandal	Dy.CMM-II/HJP
Shri Anil Kumar Singh	AMM/TRS/SPJ

S. N.	Observation	Action by
(A)	Inspection of TRS/SPJ	
3.1	<p>Cutting of bushes is being done in TRS/SPJ. A lot of scrap items have been found inside these bushes. All the scrap items in the TRS/SPJ premises may be sent to adjoining scrap yard at SPJ in next 30 days. All the scrap item in the LOCO shed be also shifted.</p> <p><u>NO SCRAP SHALL BE SOLD BY Sr.DMM henceforth, whose location is inside TRS/SPJ.</u> There is ample chance for mis-delivery. All scrap needs to be shifted to the adjoining scrap depot and then be sold.</p>	Sr.DME(Dsl)/SPJ Sr.DMM/SPJ AMM/TRS/SPJ
3.2	<p>New Brake Blocks, Battery Box, Gear Case Assembly and other ALCO Loco items were found inside the bushes scattered here and there. All new items needs to be collected and taken into books if not in accounts and old scrap items be shifted to Scrap Yard.</p>	Sr.DME(Dsl)/SPJ Sr.DMM/SPJ AMM/TRS/SPJ
3.3	<p>One DMS of Ward is remaining absent for long periods. He may be taken up and divested from ward duty.</p>	Sr.DMM/SPJ AMM/TRS/SPJ
3.4	<p>There shall be only 3 wards in the depot instead of 6 at present. One for ALCO items and 2 for Electric Loco items. All the materials may be shifted/ book transferred accordingly.</p> <p>The depot will stock items of only Group 10-19 and 20-29.</p> <p>All other common general items like chemicals, clothing etc. be stocked only in GSD/SPJ. The shed may collect these items on monthly/trimonthly basis directly from GSD/SPJ.</p> <p>The depot has been neglected for a long time. Due to which the material is not at all arranged and kept properly. Sr.DMM will visit this depot on alternate days till the situation improves. All materials in open should be shifted inside wards (except very few) on mezzanine floor or on ground floor racks (in next 30 days).</p>	Sr.DMM/SPJ AMM/TRS/SPJ
3.5	<p>Nickle Cadmium Batteries was found lying in open area received about 3-4 months back. It may have deteriorated or have become defective. The concerned DMS should be taken up immediately and a recorded warning be issued to AMM for supervisory failures.</p>	Sr.DMM/SPJ AMM/TRS/SPJ
3.6	<p>Extension of the SPJ LOCO shed is being undergoing. However, in the estimate, no provision for any additional wards for stores</p>	PCEE/ECR

	<p>depot have been kept despite the fact that there is paucity of space and many materials are lying in open in the depot.</p> <p>One open shed north of the existing ward may be created of about 10-15mtrs x 60 mtrs. Railway line coming between the two wards may be closed and sold as now a days no depot item is received/delivered by Railways in Store Vans. Alignment of adjoining Railway lines to be shifted east ward for space creation.</p> <p>SMM/C&W and Sr.DMM will plan for this shed and the work may be undertaken by adding a new item in the ongoing estimate/contract or through variation of the same.</p>	<p>DRM/SPJ Sr.DMM/SPJ</p>
3.7	निरीक्षण के दौरान एक वी०पी०यू० (नंबर-93835) पाया गया। उक्त वी०पी०यू० को तत्काल सामग्री रखने हेतु गोदाम के रूप में उपयोग में लाया जाए।	<p>Sr.DMM/SPJ AMM/TRS/SPJ</p>
3.8	रेल लाईन पर एक 1969 का ट्रॉली पाया गया। साथ ही लोको शेड से संबंधित अन्य मद भी यत्र-तत्र पाया गया। उक्त सभी का यथाशीघ्र निस्तारण सुनिश्चित किया जाए।	<p>Sr.DMM/SPJ</p>
3.9	सभी वार्ड का गेट/शटर काफी पुराना हो गया है जिसे तत्काल बदलवाने की आवश्यकता है। सभी शटर को मोटराईज शटर में परिवर्तित किया जाना सुनिश्चित किया जाय। इसे Sr.DMM खुद खरीद कर लगवा सकते हैं।	<p>PCEE/ECR Sr.DMM/SPJ</p>
3.10	लोको शेड के निरीक्षण के दौरान कुछ Over age लोको पाये गये। उक्त लोको का यथाशीघ्र निस्तारण सुनिश्चित किया जाय।	<p>DRM/SPJ Sr.DMM/SPJ</p>
3.11	<p>More than 500 items of Alco locos are surplus in depot. All these items needs to be examined by survey committee and needs to be disposed if deteriorated or is obsolete.</p> <p>Progress of surveying is too slow. 200 items be surveyed every month.</p>	<p>Sr.DMM/SPJ SrDME(Dsl)/SPJ AMM/TRS/SPJ</p>

The compliance of inspection note be sent within 30 days.

विजय
कुमार

Digitally signed
by VIJAY KUMAR
Date: 2025.12.23
17:13:09 +05'30'

PCMM/ECR/HJP

File No. ECR-HQ0STR(TP)/2024 (Comp.No. 273574)

Distribution (in e-office):

- (i) **PCEE/ECR, DRM/SPJ, ADRM/SPJ**: for information please (item No. 3.6 & 3.10)
- (ii) **Sr.DMM/SPJ, Sr.DME(Dsl)/SPJ, SMM/C&W, AMM/TRS/SPJ** : for information & necessary action pl.
- (iii) All CMMs, Dy.CMM-II : for information & necessary action pl.