

पूर्व मध्य रेल



कार्यालय
महाप्रबंधक(एसएण्डटी)
हाजीपुर - 844101

167

No.ECR/S&T/Sig/Tech/185/Pt.VIII

1975


Dated : 30/09/2019

Sr.DSTEs
E.C. Railway,
DHN, DNR, MGS, SEE & SPJ.

Sub : Functioning of BPAC and associated Axle Counter.

It has been observed that Axle Counter associated with BPAC is frequently being by-passed in case of failure. This is grossly unsafe practice and it should be stopped henceforth. In no case Axle Counter should be by-passed and efforts should be made to rectify the failure.

Divisions may enter into AMC or alternatively stock enough spares. Wherever Axle Counter has been by-passed, a time bound "Action Plan" should be made to rectify all such Axle Counters(BPAC) in next two months time. Any lapse on this account will be viewed seriously.


30/09/2019
(Rajesh Kumar)
P.C.S.T.E.

o/c