


PCE's Circular No. 14/2007/Works

Sub- Benches around the trees on Platform.

Benches are being constructed around the trees on platforms. During recent inspection of PCE in one of the division it was found that adequate clearance between trees and benches are not being kept during construction of benches causing damage to benches due to growth of the girth of the trees.

Therefore in future in all such cases the inner dia of circular benches must be kept at least $d+2m$ where d is the mean dia of the tree at bench top level in metre subject to minimum of 2.5m. Before fixing the location of the benches, required clearance of SOD must be ensured.


12/7/07
(A.K. Dubey)
Chief Engineer/Works

Docket No. W-2/118/09/Works Policy/25

Dated. 12-06-07
73

- Copy- 1. DRM/DNR, DHN, MGS, SPJ & SEE
2. Sr.DEN/(Co-ord)/DNR, DHN, MGS, SPJ & SEE.
3. All HODs Engg. Deptt./ECR/HJP