EAST CENTRAL RAILWAY

Inspection note of Shri Vijay Kumar, PCMM/ECR on visit to Divisional Stores Depot SPJ, Samastipur Divisional Office, Capital Stores Depot & New Scrap Depot, on 19.06.2024.

Inspection Note No. 06/2024 dated 04-07-24

Officials present:-

1.	Shri Gaurav Kumar Singh,	Sr.DMM/ECR/SPJ
2.	Shri Mahanand Jha,	Sr.DME/DSL/SPJ
3.	Shri Rajesh Kumar Masih,	AMM/CSD/SPJ
4.	Shri Anil Kumar Singh,	AMM/DSD/SPJ
5.	Shri Chandra Kishore,	APO/WS/SPJ

S.N	Observation	Action by
0.	Increation of DCD /CD I.	
1.	Inspection of DSD/SPJ:	
1.1	a) DSD/SPJ office building is a very old & has heritage value. The front portion of same should not be demolished. If required backside of the building may be used for further augmentation.	Sr.DMM /SPJ AMM/D/SPJ
	b) There is no turbo ventilator on the roof top of any Wards. The same be installed in adequate number so that intense heat inside the godown is minimized in Summers.	
	c) Adequate racking system is not available in godowns. Hence, the same may be planned. Semi Automatic Stackers and Forklifts may also be planned for Material Handling. All activity of loading/ unloading/ stacking be mechanized.	
	d) Flooring of almost all godowns & platform were found in damage condition or not suitable for MH equipments. Godowns floors need to be repaired with PCC+ironite /suitable flooring. The pathways are broken at many places. The same may be repaired and mastic top be provided over it.	
	e) A dock leveler with ramp for mechanized unloading/loading of material to be installed at suitable location so that material may be loaded and unloaded efficiently without any damage to the materials.	
	f) Recently CRIS has rolled out many new modules like UDM, e-dispatch, warranty management etc. regular training for staffs must be organized. Old Sale section may be	

		T
	developed as training room after necessary repair.	
	g) Entry Gates of all godowns must be increased	
	to appropriate size so that forklift may enter	
	into godown easily.	
	h) Although few CCTV cameras were installed in	
	the depot but the same is insufficient. Suitable	
	number of CCTV may be planned for	
	monitoring of all vital activity like receipt/dispatch of material to all wards.	
	i) The weigh bridge of DSD/SPJ is not found	
	working. Hence, it needs to be surveyed and if	
	not in repairable condition, then the same	
	should be disposed off as soon as possible.	
	Parallelly new proposal should also initiate for	
	installation of new one. Monthly checking as	
	per stores code for weighbridge be also ensured.	
	j) Entire area of GSD must be isolated with tie	
	bar type or suitable fencing at suitable	
	locations.	
	k) Depot officer will make preliminary planning/	
	layout on Google map/ sketches etc. within	
	next 7 days and discuss with HQ.	
1.2	Blankets & other material were lying rejected in	1 ' '
	receipt section since years. All rejection cases beyond	J
	3 months must be cleared within 15 days (non advance Paid cases) after following extant rule. The	
	online Recovery Advice of advance Paid Cases be	
	raised in next 3 days and the cases be cleared within	
	45 days with recovery as per extant rules.	
2.	Meeting with DRM & Other branch officer of SPJ Di	
2.1	Although the Division sale is good but offering of	DRM/SPJ
	Rails/P-way is not at par with proportionate target. In Apr-2024, total of 4771 Scrap Rail/P-way was	ADRM/SPJ
	mapped for offering in 1 st quarter but 2563 MT is not	Sr.DEN/Co. /SPJ
	yet uploaded in TMS even after 3 months. This	Sr.DMM/SP
	quantity be offered in next 15-20 days.	J
2.2	Benefits of recently introduced UDM and warranty	
	management were explained to branch officers. They	DRM/SPJ
	should use these modules actively which will make	SrDMM/SPJ
3.	their job easier. Inspection of capital stores depot, SPJ	
0.	The Depot must be vacated for storing only Electric	
	loco items. The Dsl loco Items be shifted to main	
	GSD premises.	CMM/IV/EC
		R
	o) All pending DDDs > 15 derve he alcowed in a serie	011DD /D 00
	a) All pending DRRs > 15 days be cleared in next 7 days. Target as per RB is 7 days.	CMPE/ECR Sr.DMM/SP

- b) Many old records are lying in depot. Hence, such records may be weeded out as per extant guidelines. It may be ensured that the records pertaining to pending DRRs etc are retained as well as those cases where there is a vigilance/Audit/Court case if any.
 - J Sr.DME/DS L/SPJ AMM/PTRU AMM/D/SP J
- c) Items pertaining to group 16-19 (used in HHP Locos) may be transferred to PTRU through DTI in 7 days. Similarly all Alco New Items at PTRU be shifted to SPJ for further use/ disposal.
- d) All scrap items are laying in depot should be sent to Scrap depot through DS-8 in 10 days.
- e) NO items of DSL/CSD/SPJ or Shed may be sold as is where basis except turning-boring. All other small/cranable items be shifted to scrap yard and sold from scrap yard only which is situated next door.
- f) GSD depot may accommodate 9-10 locos. the offered DSL Locos for sale should be shifted to GSD/SPJ.
- g) Store Van, BoxN Wagon & wheel sets are lying in front of CSD/SPJ office which are unnecessary occupying the space. These may be shifted out to other place sold if scrap/ of no use. The released space may be used for temporary placement of remaining 4-5 offered DSL locos for sale.
- h) The PH-42 work of Conversion of Dsl loco shed to Electric loco shed is not commencing as Condemned Alco locos/ electric locos are lying on the lines on planned area. The same may be vacated by shifting locos as per (g) and (f) above. Electric Locos be shifted else where.
- i) All the materials which has already been issued to DSL/SPJ are lying in stores area may vacated within three days by SSE/DSL/SPJ or returned back on DS-8.
- j) All surplus Alco items be put up to survey committee for examination. If some have deteriorated/ due to prolonged storage, the same be mentioned in survey sheet and after sanction be disposed off. The disposal of other surplus items be also processed and examined by Survey Committee.
- k) The list of Alco Diesel items approved by GM may be purchased within 15 days through

File No.ECR-HQ0STR(TP)/5/2024-O/o PCMM/HQ/ECR-Part(1)

	local purchase.			
	 The above instructions be monitored by CMPE & CMM/IV. 			
4.	Inspection of New Scrap Depot/ SPJ			
4.1	 a) During the visit of NSD/SPJ, burnt godowns were found. The angle channel & structure of burnt godowns at top portion may be assessed and form lots accordingly for sale. The direction for start of Cutting be also mentioned in the lot. Bottom portion of Godown with brick work may be retained. b) Scrap laying the in front of main gate, i.e. SMPS, Copper wire, pillow & MS should be offered within a week by making suitable lots. c) Scraps materials are lying under bushes/shrubs have overgrown at the ground inside which scrap is not visible. A quotation contract should immediately within next 10 days be entered into for uprooting the bushes from the root as well as for formation of lot for different categories of scrap item lying under 	Sr.DMM/SP J AMM/D/SP J		
4.2	bushes since ages. Several small similar categories of lots are lying on- offered. All such lots must be offered immediately by making suitable lot number say if N numbers of similar category of lots are available, then these may be numbered as sublots like 1/N, 2/N,N/N etc and sold as an integrated lot with stipulating delivery sequence.	Sr.DMM/SP J AMM/D/SP J		

The compliance of the inspection note may be sent within 30 days.

PCMM/ECR

Distribution: (in e-office):-

- (i) Secy. to GM:- For kind information of GM/ECR.
- (ii) DRM/SPJ, PCEE/ECR (Para 3.0) , CMPE/ECR (Para 3.0) : for information and n.a. pl
- (iii) All CMMs, All stores Officers
- (iv) Sr.DME/DSL/SPJ, Sr.DMM/SPJ
- (v) AMM/D/SPJ & AMM/DSL/SPJ.
- (vi) PS to PCMM: to post all inspected points in inspection Module.