



HARNAUT



* 4(DM), 6(DM), 8(DM), 104(DM), 106(DM), 108(DM), 202(DM), 204(DM)



VDU DETAILS:-
 MAIN SIG. : 1,2,3,4,5,6,7,8,11,12.
 CALLING ON SIGNAL: C-1, C-12.
 POINT : 51,52,53,54,55,56,59,60.
 CRANK HANDLE: CH-1,CH-2,CH-3,CH-4,CH-5,CH-6,CH-9,CH-10.
 L-XING GATE CONTROL:- G-31,G-32,G-33.
 DEAD SHUNT:- DSH-310,302,303.