EAST CENTRAL RAILWAY

Office of the General Manager (Safety) Hajipur

Dated: 01.04.2025

No. ECR/Safety/Safety Calendar/2025-26

Divisional Railway Manager, East Central Railway, DHN, DNR, DDU, SEE & SPJ.

Sub: Safety Calendar for 2025-26.

Ref: Railway Board's letter No. 2025/Safety-(Imp)/3/Safety Calendar dated 13.03.2025.

Please find herewith Safety Calendar for the year 2025-26 issued by Railway Board for necessary action at your end.

You are requested to arrange to take necessary action and submit reports of safety drive launched in your division as per the above safety calendar to this office after completion of drive period every month.

DA/- As referred letter.

(Goverdhan Kumar) Dy.CSO/Electrical/HJP For PCSO/ECR

Copy to:

- 1. PCEE, PCME, PCSTE, PCOM & PCE for information and necessary action please.
- 2. Sr.DSO/ECR/DHN, DNR, DDU, SEE & SPJ for information and necessary action.



भारत सरकार (GOVERNMENT OF INDIA) रेल मंत्रालय (MINISTRY OF RAILWAYS) रेलवे बोर्ड (RAILWAY BOARD)



No.2025/Safety(Imp)/3/Safety Calendar

New Delhi, Dated: 3.03.2025

सचिव

The General Managers,
All Zonal Railways &
Managing Directors, KRCL and DFCCIL.

Sub: Safety Calendar for 2025-26.

A Safety Calendar for the year 2025-26 has been prepared. A copy of the same is enclosed herewith. These week long monthly safety drives should be carried out during the second week of each month, beginning from Monday.

The aspects mentioned in this calendar are only indicative in nature; Zonal Railways should issue their own comprehensive drive, including suitable checklist for inspecting Officers/Supervisors. Officers of various departments from HQ should also be involved. Effective follow up action should be taken on all deficiencies and irregularities noticed during the drive. PCSOs should be directed to critically analyze data to identify systemic deficiencies. Results of the monthly drive, bringing out systemic deficiencies and action taken/planned to be taken with timeline, should be sent to the Board by the end of third week of the month. Apart from sending hard copy, the report should invariably be uploaded on SMDMS, both in PDF and DOC format and may also be e-mailed at edeesafety@gmail.com and safetyimp46@gmail.com.

(Ashok Kumar Nakra)

अशोक कुमार नाकरा

Executive Director/EE/Safety कार्यकारी निदेशक/ई.ई./संरक्षा

Phone/फोन: 011-23047427

SAFETY CALENDAR 2025-26

APRIL:

TRD: Drive for OHE structure such as Check rail level, Tilting of masts, Condition of embankments with respect to stability of masts, Condition of location number plate, etc.

CREW: Crew Competency, Breath Analyzer Machine in Working order or not and CMS integration with BA, Spare BA availability.

LOCOMOTIVES: Under carriage drive such as adequate level of suspension bearing oil and its filling cap, Cardium compound in gear case and its cover, felt wick carrier screw and its sealing and mounting brackets and strength of under frame equipments.

SPAD Drive:-Drive to prevent SPAD cases.

Footplate inspections, especially during night hours.

Ambush checks of running staff by loco inspectors to check calling out of signals loudly and clearly by the LP and the ALP; whether the ALP is holding the RS valve while passing the signal at yellow; whether the LP/ALP is using mobile phone while on run.

Checking CVVRS recordings, where available, for the above to identify and counsel erring LPs/ALPs

Specific monitoring of crew regarding his train control on yellow signal and train control in gradients so as to stop promptly at Red signals; control of trains in automatic block system. Train driving in Automatic Block Sections to be checked from SPM records also.

Following all speed restrictions meticulously.

Monitoring of crew's braking technique for different types of load

Following of prescribed speed restrictions for BMBS rakes.

Checking for any medical condition, medications (prescribed by both Railway and Private doctors) that may affect train driving

Checking for foot plating of full beat by assigned loco inspectors

Family counseling sessions being organized, their quality and attendance therein

Road learning of track machine operators and tower wagon operators, and their competency certificates

Checking of crew links where adequate rest is not built in practically

ELECTRICAL

COON W

Thorough intensive inspection of crew lobbies; checking manual booking of crew - frequency and reasons

Monitoring that unusual reported by crew are addressed quickly

Checking that genuine grievances of crew are addressed promptly

Thorough intensive inspection of running rooms; quality of rest availed by LP/ ALP in Running rooms & Headquarters

Monitoring of proper road learning, availability of appropriate competencies of crew driving a particular type of train, no ⋄verdue examination, training or courses.

Ensuring that LP/ ALP have understood and acknowledged all circulars timely.

Quality and effectiveness of modification of Emergency brake valves in locomotives

Special monitoring of train driving in one-train-only sections, where such working is in practice, by checking of loco SPM records for proper stopping, etc.

Signal sighting issues, Caution indicators, Sigma Boards, RHS locations, intermediate signal locations, vulnerable signal locations where only one crew member can sight the signal, and specific location of starter signal for a particular line during departure from stations, to be specifically checked, identified and observed during footplate.

Proper signal exchange

ELECTRICAL

Provision and proper working of fog-safe devices in regions affected by fog

Availability of Sufficient No of Walkie Talkie Sets & Spare Batteries

Lookout of any poor worksite protection, possible infringement by stray material, vehicle - especially careless cases where infringement was saved by very narrow margins/ providentially.

Working beyond stipulated hours of duty of running staff may lead to fatigue and should be prevented. It should be ensured that LPs and ALPS are given adequate outstation rest as stipulated.

Detailed and intensive inspection of crew lobbies at officers' level.

Counseling of all loco inspectors at officers' level.

Unusual reported by crew should be monitored and addressed.

Masson 1

1	To check and ensure fitment of side frame key, shackle lock, Pivo to pin washer in wagons.	
MECHANICAL	To ensure checking of CBC including APMs, Knuckle, lock lifter assembly, Knuckle pin, Anti rotation lug, Coupler heads, etc. Also checking of coaching couplers for the relevant items and in addition shim heights etc. Condition of operating handle, including bends, wear of bolts, corrosion in brackets, groove in bore of bracket etc. Condition of supporting device and its springs. Check all the gauges for very measurement in CBC along with calibration records of these gauges for concurrency. Also to check the availability and quality of tertiary locking pin in coaching CBC, where required to be provided. Also to check the availability and quality of secondary locking pin in coaching CBC, where required to be provided	
3,00	Check Side buffers in locomotives and coaches for height, drooping and cracks in the casting, completeness of bolts securing them with the rolling stock. Maintenance of draft gear in workshops including loose bolts, external	
AND THE REAL PROPERTY.	damage, seating in pocket, condition of buff plate and application of grease, pre-load value, condition of spring column.	
S&T	To check & ensure working of Data logger & its networking with Central System at Divisional HQ	
popilis are chage	Check to ensure proper working of DC Track Circuits in Rusty Rail Area.	
	To check whether Both Track detection devices are working normally where Dual detection is provided.	
70 2567	Proper Working of Earth Leakage Detector & Fire Alarm System.	
OPERATING	Ensure that securing of vehicles in the running line/yard is being done as per extant rules. Shunting operations should be done and monitored strictly in accordance with	
ENGINEERING	the GR & SR. Preparation of Hot Weather Precautions ensuring zero missing fittin completeness of ballast profile including De-stressing of LWRS	



MAY:

ELECTRICAL	TRD: Drive for Bonding such as Open or loose bonds, Bond missigng, etc.
	CREW: Availability of safety equipment in locomotive
	1. 图2. 化工程设施设施的设施设施设施设施设施设施设施设施设施设施。
	TRACTION: Above roof drive such as cleaning, joint with TrD sta ff etc.
MECHANICAL	Drive on fire protection measures in coaches including working of fire detection system in AC coaches, fire detection and suppression systems in Pantry Cars and Power Cars. Check the locking of aut omatic suppression system magnet valve in FDSS and locking arrangement for brake system isolation cut out cock in FSDS.
am prieton d	Check the locking of automatic suppression system magnet valve in FIDSS and locking arrangement for brake system isolation cut out cock in FS-DS.
MINE COA	Availability, condition and cross-check of schedule overdue of
7	portable fire extinguishers provided in coaches.
-	Process audit of spring section in workshops.
S&T	All Veeder Counters in Station should be cross checked with Register for matching of number and proper reason
dation having	Obstruction Test of Interlocked Point as per SEM to ensure their safe working Ensure that Roof of Relay Room, IPS Room and Battery Rooms are clean
	and Water Drains are not choked.
OPERATING	Proper Working of Lightning and Surge protection devices. Updating of SWR as per the physical condition of yard
OFERNING	opulating of Swit as per the physical condition of yard
	SWR should be updated from time to time with the last date of
sent good no	updation and if any further change has been made, the correction slip issued after the last updation should be available.
(C)	The Station working diagram should be available and it should
STATE STREET,	conform to the existing layout of the station.
	The Station Working Rule should be available with Station Master, Cabin Incharge and Yard Master.
ENGINEERING	Drive for checking Hot Weather Patrolling of track

mey

JUNE:

JUNE:	Company Assessment of the company of
ELECTRICAL	TRD: drive for insulators such as Chipped or damaged insulators , Flash over mark on insulators, etc.
	CREW: Crew Road learning drive
Personal Person Ga	TRACTION: Summer drive, which includes temperature checking of exle
	box, MSU and TM bearing through Infrared temperature gun on arr ival
	of locomotive at destination station/ out pit, checking for any oil
	leakage from transformer, Tap Changer (GR), MPH circuit, traction
	converter, oil pump etc.
MECHANICAL	Safety of underslung equipment in rolling stock
Tall self-proper	Audit of rolling in and rolling out examination points
S&T	To check and ensure that all field equipments/machines of S&T such as Point Machines, Axle Counter devices including Cables etc are properly inspected for their safe condition before monsoon
det in the state of	Availability of Completion Plans.
OPERATING	Proper maintenance of registers by the Station Master as per the laid down norms. Proper maintenance of the following registers should be checked from the safety point of view:
	Caution Order Register
barths	Train Signal Register
	Accident Register
and the second second	Files of Safety Circulars/Safety Bulletins
ANALYSI MISIPE	Signal disconnection and reconnection register Night inspection register
ENGINEERING	Pre-monsoon precautionary measures
yethersen seg Venton o	Maintenance of side/catch water drains, bridge waterways, painting of HFL, FSL, DL, selection of Patrolmen and Watchmen, Inspection of rain gauges, Inspection of RAW/RAT, review of vulnerable location, arrangement of materials for emergencies & other actions as per IRPWM.
2770.0	Yard drainage, clearance of rail flange with ballast, recoupment of insulated liners etc



JULY:

TRD: drive for regulating equipment of OHE such as Tilting of anti-falling device, Free movement of auto-tensioning device etc.

CREW: SPAD drive

TRACTION: Monsoon drive, which includes working of wiper, condition of silica gel, topping up of water in batteries etc.

SPAD Drive:-Drive to prevent SPAD cases.

ELECTRICAL Footplate inspections, especially during night hours.

ELECTRICAL

Ambush checks of running staff by loco inspectors to check calling out of signals loudly and clearly by the LP and the ALP; whether the ALP is holding the RS valve while passing the signal at yellow; whether the LP/ALP is using mobile phone while on run.

Checking CVVRS recordings, where available, for the above to identify and counsel erring LPs/ALPs

Specific monitoring of crew regarding his train control on yellow signal and train control in gradients so as to stop promptly at Red signals; control of trains in automatic block system. Train driving in Automatic Block Sections to be checked from SPM records also.

Following all speed restrictions meticulously.

Monitoring of crew's braking technique for different types of load Following of prescribed speed restrictions for BMBS rakes.

Checking for any medical condition, medications (prescribed by both Railway and Private doctors) that may affect train driving

Checking for foot plating of full beat by assigned loco inspectors

Family counseling sessions being organized, their quality and attendance therein

Road learning of track machine operators and tower wagon operators, and their competency certificates

Checking of crew links where adequate rest is not built in practically

Thorough intensive inspection of crew lobbies; checking manual booking of crew - frequency and reasons

Monitoring that unusual reported by crew are addressed quickly

Checking that genuine grievances of crew are addressed promptly

Thorough intensive inspection of running rooms; quality of rest availed by LP/ ALP in Running rooms & Headquarters

my -

Monitoring of proper road learning, availability of appropriate competencies of crew driving a particular type of train, no overrdue examination, training or courses. Ensuring that LP/ ALP have understood and acknowledged all circulars timely. ELECTRICAL Quality and effectiveness of modification of Emergency brake valves in locomotives Special monitoring of train driving in one-train-only sections, where such working is in practice, by checking of loco SPM records for proper stopping, etc. Signal sighting issues, Caution indicators, Sigma Boards, RHS locations, intermediate signal locations, vulnerable signal locations where only one crew member can sight the signal, and specific location of starter signal for a particular line during departure from stations, to be specifically checked, identified and observed during footplate. Proper signal exchange Provision and proper working of fog-safe devices in regions affected by Lookout of any poor worksite protection, possible infringement by stray material, vehicle - especially careless cases where infringement was saved by very narrow margins/ providentially. Working beyond stipulated hours of duty of running staff may lead to fatigue and should be prevented. It should be ensured that LPs and ALPS are given adequate outstation rest as stipulated. Detailed and intensive inspection of crew lobbies at officers' level. Counselling of all loco inspectors at officers' level. Unusuals reported by crew should be monitored and addressed. MECHANICAL Drive to ensure that all outlines are free of water logging, clearing of drainage, availability of pumps Drive to see that wagon maintenance facilities do not have slush and mud in circulating areas and there is no excess vegetation that can harbour snakes etc. Ensure that all lights in yards for night examination are working

Ensure no leakage of current, sparking, overheating joints at power supply to pit lines, examination points with welding and lighting facilities

Mary.

s and magnitude of the second	Drive to check that there is no water ingress into the electrics of coaches.
S&T	To check and ensure effectiveness of interlocking at L.C gates and all S&T items
	Availability of TRD Bonds.
OPERATING	Observing monsoon precaution
anuthor 318	Coordination with Engineering Department for movement of materials at vulnerable locations
Tanga sansar 1 salaafilanda sal	Informing Engineering Department officials about heavy rains, thunderstorms, etc. affecting the movement of trains.
ENGINEERING	Monsoon Patrolling, both stationary and mobile, as per Monsoon Booklet, inspection of equipment of Patrolmen, Inspection of Patrol Books by Engineering Officials, checking over patrolling at night
MALE WE WARD	Joint yard inspection.

AUGUST:

ELECTRICAL	TRD: drive for OHE Conductor, such as damaged strands of catenary or
ELECTRICAL	any other stranded wire, Condition of PG clamps and jumpers etc.
derivation	CREW: Running room drive such as facilities and amenities (water purifier, water cooler, good quality of utensils etc.)
	TRACTION: Drive for working of Air drier, sanders and wipers etc.
MECHANICAL	Electrics in coaches: unnecessary bypassing of circuits, rough jumper wires, bypassing of fuses, damage to switches, exposed electrical panels, working of air dryers and wipers in self propelled stock. Audit of wheel shops in workshops
	Audit of proper working of M&Ps for wagon maintenance in freight depots.
5&T	To check and ensure whether maintenance & testing of Signal Equipment are regular as per Maintenance Schedule prescribed and as per prescribed procedure
16560	Checks regarding double locking arrangement in Relay Room & maintaining proper entry in Register
OPERATING	Inspection of Guard Van – Following Safety Equipments to be checked in the Guard Van:
	General and Subsidiary Rules

in

	Working Time Table Detonators with expiry date Red Flag (2 Nos.) and Green Flag (1 No.), Tail Board (1 No.) Air Pressure Gauge with quick coupler
10-30-124 P	Pad locks Walkie-Talkie in operational condition Wooden wedges / skids (2 Nos)
ENGINEERING	Work site protection specially LHS/RUB and works being carried out near the track

ELECTRICAL	TRD: drive for cantilever assembly such as rusted/damaged fittings tubes, Height and stagger of contact and catenary wire etc.
	CREW: Abnormalities pending in section and noted by crew drive
	TRACTION :ESMON working drive
MECHANICAL	Fitment of side frame key, shackle lock, centre pivot washer in wagons CBC including APMs, Knuckle, lock lifter assembly, knuckle pin, ant rotation lug, coupler heads etc
de si o existendo el Red estrado Andreo metrorio	Also to check the availability and quality of secondary locking pin in coaching CBC, where required to be provided.
	Shim heights in coaching couplers
ATTORNEY BY SWA	Operating handle including bends, wear of bolts, corrosion in brackets groove in bore of bracket, supporting device including springs Gauges for checking of CBC including their calibration
Tenga water Silan il 1994 d Wheen-Paris	Side buffers for drooping, condition of bolts, cracks in casting. Also to check the availability and quality of tertiary locking pin in coaching CBC where required to be provided.
	Maintenance of draft gear in workshops including loose bolts, external damage, seating in pocket, condition of buff plate and application of grease, pre-load value, condition of spring column.
S&T	To check and ensure whether all axle counters used for BPAC working are functional, their resetting unit is also in working order and proper procedure is being followed by ASM/SM for resetting of BPAC after its failure
	Obstruction test on all Points as per SEM
OPERATING	Observance of Rules during abnormal working
	Proper filling of paper line clear ticket/form
syller hope POS	Proper message has been exchanged between Station Master and Loco Pilot / Guard



	Proper filling of forms to operate the train during Total Failure of Communication (TFC)	
ENGINEERING	Drive of checking of USFD Testing including ADEN/Sr DEN	

OCTOBER:

TRD: drive for isolators assembly, such as for signs of sparking or overheating of isolators, Condition of locks/interlocks, Alignment of contacts and arcing horns etc.

CREW: Clear visibility of signal to crew in day and night

TRACTION: Drive for cable protection such as to ensure proper cable laying in junction boxwith gland and vinyl housing, no loose hanging cable etc.

SPAD Drive:-Drive to prevent SPAD cases.

SPAD Drive:-Drive to prevent SPAD cases.

Footplate inspections, especially during night hours.

ELECTRICAL

Ambush checks of running staff by loco inspectors to check calling out of signals loudly and clearly by the LP and the ALP; whether the ALP is holding the RS valve while passing the signal at yellow; whether the LP/ALP is using mobile phone while on run.

Checking CVVRS recordings, where available, for the above to identify and counsel erring LPs/ALPs

Specific monitoring of crew regarding his train control on yellow signal and train control in gradients so as to stop promptly at Red signals; control of trains in automatic block system. Train driving in Automatic Block Sections to be checked from SPM records also.

Following all speed restrictions meticulously.

Monitoring of crew's braking technique for different types of load

Following of prescribed speed restrictions for BMBS rakes.

Checking for any medical condition, medications (prescribed by both Railway and Private doctors) that may affect train driving

Checking for foot plating of full beat by assigned loco inspectors

Family counseling sessions being organized, their quality and attendance therein

Road learning of track machine operators and tower wagon operators, and their competency certificates

of my

S&T	Ensure double locking arrangement in Block Instrument Proper observance of rules during disconnection of Points & Signals Ensure double locking arrangement in Block Instrument.
OPERATING	Proper rules should be followed at the time of train parting
ebolicyc few to	Test of knowledge of duties of Guards and Loco Pilots to handle train parting Protection of train by Guard using various methods prescribed in GR / SR
ENGINEERING	Inspection of Level crossing gates: To check and ensure adequate visibility for both Train Loco Pilot and Road users at Level Crossing gate, adequacy of equipment, condition of road and speed breakers, locking arrangement, condition of booms

NOVEMBER:

ELECTRICAL	TRD: drive for section insulators such as badly chipped or slightly
LLECTRICAL	cracked, dust and dirt accumulated on insulators Flash-marks on runners etc.
constitute the constitute of the state of th	CREW: speed monitoring device chart analysis. Counsel running staff regarding working of trains during poor visibility condition like foggy weather etc.
ye sa Alla mere	TRACTION: Drive for winter such as Re-greasing of pantograph servomotor to avoid jamming, Working of heaters/blowers in both cabs, Air-tightness of cab main doors, window shutter, sand sea ling of ventilator covers and Proper level of oil to be maintained in TFP, Grand
	Traction Converter etc. Silica gel for transformer, Tap charger and traction converter must be in good condition. Air dryer must be in working order and isolation should not be permitted.
MECHANICAL	Audit of welding facilities and practices in workshops and maintenance units. Audit of brake system testing practice using SCTR, SWTR and RTR Audit of brake system testing practice using SCTR, SWTR and RTR.
S&T	To check and ensure whether proper sealing is being done of Control Panel, Block Instruments, HKT box, CH box etc. Checking visibility of Signals
OPERATING	Observing precautions during foggy weather Availability of Fog Safety Device in working condition in Loco Adequate availability of detonators with the Guard Availability of Visibility Test Object (VTO)

week-

Checking of crew links where adequate rest is not built in practically Thorough intensive inspection of crew lobbies; checking manual booking of crew - frequency and reasons Monitoring that unusual reported by crew are addressed quickly Checking that genuine grievances of crew are addressed promptly Thorough intensive inspection of running rooms; quality of rest availed by LP/ ALP in Running rooms & Headquarters Monitoring of proper road learning, availability of appropriate competencies of crew driving a particular type of train, no over-due examination, training or courses. Ensuring that LP/ ALP have understood and acknowledged all circulars Quality and effectiveness of modification of Emergency brake valves in locomotives Special monitoring of train driving in one-train-only sections, where such working is in practice, by checking of loco SPM records for proper Signal sighting issues, Caution indicators, Sigma Boards, RHS locations, intermediate signal locations, vulnerable signal locations where only one crew member can sight the signal, and specific location of starter signal for a particular line during departure from stations, to be specifically checked, identified and observed during footplate. Proper signal exchange Provision and proper working of fog-safe devices in regions affected by Lookout of any poor worksite protection, possible infringement by stray material, vehicle - especially careless cases where infringement was saved by very narrow margins/ providentially. Working beyond stipulated hours of duty of running staff may lead to fatigue and should be prevented. It should be ensured that LPs and ALPS are given adequate outstation rest as stipulated. Detailed and intensive inspection of crew lobbies at officers' level. Counselling of all loco inspectors at officers' level.

MECHANICAL

Audit of ARTs and their equipment. Audit of bogie frame maintenance.

Unusuals reported by crew should be monitored and addressed.

Weeks!

	Observance of speed limits by Loco Pilot during Foggy weather
ENGINEERING	Intensive check of Cold weather patrolling: knowledge of patrolmen, adequacy of safety equipment, Provision of GPS to the patrolmen, availability of patrol book etc.

ELECTRICAL	TRD: drive for level crossing such as Structural soundness of height gauges at level crossings, Condition of caution and warning boards etc.
	CREW: drive to reduce the number of registers maintained in lobbie s.
ionalignale Life programme Connection	TRACTION: Drive for working of all safety equipment provided such a fire extinguisher, VCD, head light, flasher light etc
yangata ng ayon	Availability of fog safety device in working condition in loco. Observance of speed limits by loco pilot during Foggy weather. Protocol for cab changing/crew changing.
MECHANICAL	Review material availability for safety items, fund availability, AAC, mext year projections, storage in stores depots, Training of manpower, periodical refresher, identify areas of weakness in material availability and manpower training and address them.
S&T	To check and ensure whether Approach Locking, Track Locking and Back Locking is effective all the time
OPERATING	Observing precautions during foggy weather Availability of Fog Safety Device in working condition in Loco Adequate availability of detonators with the Guard Availability of Visibility Test Object (VTO) Observance of speed limits by Loco Pilot during Foggy weather
ENGINEERING	Drive of checking of USFD Testing and welding team including ADEN/Sr DEN



JANUARY:

TRD: drive for Turn out and cross overs such as Check stagger of both the OHEs at turnout, main line OHE of overlap type turnout is about 50mm below that of the turnout OHE etc.

CREW: drive for brake feel test, RS valve handle, repeating of sigmal Proper and adequate rest at HQ and outstation.

TRACTION: Drive for under frame equipment mounting bracket sæfety. SPAD Drive:-Drive to prevent SPAD cases.

SPAD Drive:-Drive to prevent SPAD cases.

Footplate inspections, especially during night hours.

Ambush checks of running staff by loco inspectors to check calling out of signals loudly and clearly by the LP and the ALP; whether the ALP is holding the RS valve while passing the signal at yellow; whether the LP/ALP is using mobile phone while on run.

ELECTRICAL

Checking CVVRS recordings, where available, for the above to identify and counsel erring LPs/ALPs

Specific monitoring of crew regarding his train control on yellow signal and train control in gradients so as to stop promptly at Red signals; control of trains in automatic block system. Train driving in Automatic Block Sections to be checked from SPM records also.

Following all speed restrictions meticulously.

Monitoring of crew's braking technique for different types of load

Following of prescribed speed restrictions for BMBS rakes.

Checking for any medical condition, medications (prescribed by both Railway and Private doctors) that may affect train driving

Checking for foot plating of full beat by assigned loco inspectors

Family counseling sessions being organized, their quality and attendance therein

Road learning of track machine operators and tower wagon operators, and their competency certificates

Checking of crew links where adequate rest is not built in practically

Thorough intensive inspection of crew lobbies; checking manual booking of crew - frequency and reasons

Monitoring that unusual reported by crew are addressed quickly

amy

ELECTRICAL EN EN EN EN En tin Qu loc Sp wo sto Ch Pr Pr fo Lo m. sa W fat AL	horough intensive inspection of running rooms; quality of rest availery LP/ ALP in Running rooms & Headquarters Monitoring of proper road learning, availability of approperiate ompetencies of crew driving a particular type of train, no overdus xamination, training or courses. Insuring that LP/ ALP have understood and acknowledged all circular mely. Quality and effectiveness of modification of Emergency brake valves in a comotives pecial monitoring of train driving in one-train-only sections, where such orking is in practice, by checking of loco SPM records for proper topping, etc. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular have described all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular have described all circular type of train driving in one-train-only sections, where such acknowledged all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular have described all circular mely. Insuring that LP/ ALP have understood and acknowledged all circular have described
ELECTRICAL co ex En tin Qu loc str Sig int cr for ch Pr for Lo m. sa	competencies of crew driving a particular type of train, no overduct a competencies of crew driving a particular type of train, no overduct a competencies. Insuring that LP/ ALP have understood and acknowledged all circular mely. It was a competency brake valves in the competency brake valves in the competency brake valves in the competency of train driving in one-train-only sections, where such contains in practice, by checking of loco SPM records for proper topping, etc. It is a signal sighting issues, Caution indicators, Sigma Boards, RHS locations the competency of the compe
tin Qu loc Sp wc stc Sig int cre for ch Pr Pr for Lo massa	mely. Quality and effectiveness of modification of Emergency brake valves in promotives pecial monitoring of train driving in one-train-only sections, where such vorking is in practice, by checking of loco SPM records for proper tropping, etc. Ignal sighting issues, Caution indicators, Sigma Boards, RHS locations intermediate signal locations, vulnerable signal locations where only on the member can sight the signal, and specific location of starter signary or a particular line during departure from stations, to be specifically thecked, identified and observed during footplate. Proper signal exchange Provision and proper working of fog-safe devices in regions affected by the same proper signal exchange of the safe devices in regions affected by the same proper worksite protection, possible infringement by strain training the safe devices cases where infringement was aved by very narrow margins/ providentially.
Sp wo store Sig int cre for ch Pr Pr for Lo min sa	pecial monitoring of train driving in one-train-only sections, where succepting is in practice, by checking of loco SPM records for propertopping, etc. Ignal sighting issues, Caution indicators, Sigma Boards, RHS locations thermediate signal locations, vulnerable signal locations where only on rew member can sight the signal, and specific location of starter signal or a particular line during departure from stations, to be specificall thecked, identified and observed during footplate. Troper signal exchange Trovision and proper working of fog-safe devices in regions affected by the properties of
Signint cree for chemical control cont	vorking is in practice, by checking of loco SPM records for proper topping, etc. ignal sighting issues, Caution indicators, Sigma Boards, RHS locations intermediate signal locations, vulnerable signal locations where only on rew member can sight the signal, and specific location of starter signal or a particular line during departure from stations, to be specifically hecked, identified and observed during footplate. Proper signal exchange Provision and proper working of fog-safe devices in regions affected by sogo ookout of any poor worksite protection, possible infringement by stranaterial, vehicle - especially careless cases where infringement was aved by very narrow margins/ providentially.
int cre fo ch Pr Pr fo Lo m. sa W fat AL	ntermediate signal locations, vulnerable signal locations where only on rew member can sight the signal, and specific location of starter signator a particular line during departure from stations, to be specificall hecked, identified and observed during footplate. Troper signal exchange Trovision and proper working of fog-safe devices in regions affected by segundary poor worksite protection, possible infringement by stranaterial, vehicle - especially careless cases where infringement was aved by very narrow margins/ providentially.
Pr fo Lo ma sa W fat AL	provision and proper working of fog-safe devices in regions affected by pg ookout of any poor worksite protection, possible infringement by stranaterial, vehicle - especially careless cases where infringement was aved by very narrow margins/ providentially.
fo Lo mi sa W far AL	ookout of any poor worksite protection, possible infringement by stranaterial, vehicle - especially careless cases where infringement was aved by very narrow margins/ providentially.
Lo m. sa W far AL	ookout of any poor worksite protection, possible infringement by stranaterial, vehicle - especially careless cases where infringement was aved by very narrow margins/ providentially.
fa'	Vorking beyond stipulated hours of duty of running staff may lead to
W 100 Mark 100 Mark	atigue and should be prevented. It should be ensured that LPs and LPS are given adequate outstation rest as stipulated.
De	Detailed and intensive inspection of crew lobbies at officers' level.
Co	Counseling of all loco inspectors at officers' level.
Uı	Inusuals reported by crew should be monitored and addressed.
de in sc Ch FC FS	Drive on fire protection measures in coaches including working of fire letection system in AC coaches, fire detection and suppression system in Pantry Cars and Power Cars Availability, condition and cross-check of chedule overdue of portable fire extinguishers provided in coaches. Check the locking of automatic suppression system magnet valve in IDSS and locking arrangement for brake system isolation cut out cock in ISDS.
	theck the locking of automatic suppression system magnet valve in FDSS and ocking arrangement for brake system isolation cut out cock in FSDS.

. .. .

in in

tel northe	Process audit of spring section in workshops
S&T	To check and ensure the effectiveness of interlocking of LC Gates, effectiveness of Sliding Booms.
OPERATING	Guards should have proper pressure gauge Air Pressure gauge of approved size with quick coupler
	Proper functioning of pressure gauge
ENGINEERING	Lubrication of joints, gaps, survey and adjustments

FEBRUARY:

ELECTRICAL	TRD: drive for inspections of tools in OHE/PSIdepot such as Da maged strand of cable, Defective clamps, damaged strands of steel rope etc
ecapter twelv	CREW: drive to check training centres' feedback of crew training
ali Shar al	Traction: Drive for fire –prevention, such as DGA testing of transFormer oil, working of QLM, Q44 protective relays Ascertain the sealing and function of VCD in every locomotive.
MECHANICAL	Safety of underslung equipment in rolling stock Audit of rolling in and rolling out examination points
S&T	To check and ensure that proper laid down procedure is being followed for opening & closing of Relay Room and ensure that the opening and closing of Relay Room contact is connected with Data Logger. Reason is recorded clearly for opening of Relay Room. Cross check writing work on CT Rack.
OPERATING	Ensure proper setting and locking of points before allowing movement. Provision of double lock on Relay Room - one key with SM and another
Deep 120	key with S&T staff
	Transaction of every opening and closing of Relay Room are entered in the Register and signed by SM and S&T staff.
	Check if SMS is received by SM when relay room opened
ENGINEERING	Joint point and crossing drives

MARCH:

ELECTRICAL	TRD: drive for neutral section and overlap such as state of cleanliness of insulators, condition of arcing horns and arc traps and Pantograph hit marks etc.
	CREW: drive on SPAD.

My way

	Traction :Availability of safety material and unit exchange spare in sheds
MECHANICAL	Electrics in coaches: unnecessary bypassing of circuits, rough jumpe wires, bypassing of fuses, damage to switches, exposed electrical panels, working of air dryers and wipers in self propelled stock. Audit of wheel shops in workshops Audit of proper working of M&Ps for wagon maintenance in freight depots
S&T	To check and ensure whether proper procedure is being followed by S&T staff for rectification of failures of S&T equipment. To check and ensure whether proper procedure is being followed by S&T staff for testing, overhauling and maintenance of signaling equipment as per schedule.
OPERATING	Ensure proper shunting practices in the yard, duly following the laid down norms. Ensuring train operations during the signal failures in accordance with the extant rules regarding disconnections and reconnections. Speed during shunting should normally not exceed 15 kmph. The shunting should be supervised by competent railway staff.
ENGINEERING	Preparation of Hot Weather Precautions

