

## RED BULLETIN

No. ECR/Safety/Red Bulletin – JUNE, 23-24

Date: 12.07.2023

### 1. Major irregularities noticed during inspections: -

- (A) At L.C/36/B/T in DNR division, fixing of sign boards were not found proper. Here, first Speed Breaker sign board & then Gate sign board were fixed, while the proper sequence is firstly, Gate Sign Board and then after Speed Breaker Sign Board at prescribed distances as per IRPWM.
- (B) Majority of the TRD items specified for keeping in ART were not available in ART/CPU. All items as per the desired list should be made available.
- (C) In Relay Room hut at DDU in DDU division, SMS alert message for opening/closing was found not functional. Proper mapping should be ensured. Data Logger should be mapped with door opening/closing.
- (D) DN Warning Boards are faded at GAI, PSR, NNR, THB, NNA & CRR station in BJU-KIR section in SEE division. It should be retro-reflective.

### 2. All Train Accident Analysis up to June, 23:- Division- wise position.

Type	DHN	DNR	DDU	SEE	SPJ	Total
Collision	-	-	-	-	-	-
Derailment	-	01	01	-	01	03
L-Xing ( Manned)	-	-	-	-	-	-
L-Xing ( Un-Manned)	-	-	-	-	-	-
Fire in Trains	-	-	-	01	-	01
Misc.	-	-	-	-	-	-
I.SPAD	-	-	-	-	-	-
II. Breach of Block Rules	-	-	-	-	-	-
III. Averted Collision	-	-	-	-	-	-
Unusual	01	-	-	-	-	01
<b>Total</b>	<b>01</b>	<b>01</b>	<b>01</b>	<b>01</b>	<b>01</b>	<b>05</b>

### All Accident during JUNE, 2023 - 01

### 3. Items requiring special attention in JULY, 2023

#### General

- (i) Ensuring provision of infrastructure at LC Gate.

#### Operating

- (i) Ensuring proper adherence of shunting rules.  
(ii) Checking of stabled loads secured as per rules.

#### Personnel

- (i) Proper accountal of vacancy of safety category staff.

**Mechanical**

- (i) Proper securing of stabled rolling stocks in Depot/Shed.
- (ii) Intensive inspection of maintenance of wagons in yards.

**Electrical**

- (i) Checking of competency, training or PME certificates of Loco Pilot or Tower Wagon drivers.
- (ii) Intensive checking of sanders and wipers of locomotives.

**Engineering**

- (i) Ensuring Pre-monsoon precautions taken and recouping of washout repair materials as quarry dust, Sal ballah etc. at pre-nominated locations.
- (ii) Ensuring attention to Points & crossing deficiencies at regular interval.

**S&T**

- (i) Checking of effectiveness of interlocking at L.C gates and all S&T items.
- (ii) Ensuring Safety tolerance of all Signalling gears and equipment.

**Security**

- (i) Liaising with local police and civil authority regarding suspected unsocial activities threatening safety of trains.

**Commercial**

- (i) Preventive measure to prevent fire in tank wagons during loading and unloading.

**(Sunil Kumar)**  
**Dy. CSO/ Traffic**

**Distribution:-**

1. All DRMs/Sr. DSOs- For information & distribution to all Branch Officers for n/a.
2. Principal, ZRTI/ MFP& BLI- For information & wide publicity amongst trainees.
3. Safety Camp/DHN.