


LOOK & BLOCK INSTT.



PANEL DETAIL:

MAIN SIGNAL BUTTONS 1,2,3,4,5,6,8,11,12
 CALLING ON SIGNAL BUTTONS C-1 & C-12
 POINT BUTTONS 51, 52, 53, 54, 55, 56
 CRANK HANDLE BUTTONS CH-1, CH-2, CH-3, CH-4
 L.C. GATE BUTTONS G-31 & G-32
 SPARE BUTTONS 7, 9 & 10

- NOTE:**
1. ABSOLUTE BLOCK SYSTEM WORKING WITH BARAUNI Jn & BACHHWARA Jn.
 2. DOUBLE LINE BLOCK INSTRUMENT M.S.W. TYPE (LOCK & BLOCK INSTT) WITH BUJ & BCA
 3. AXLE COUNTER PROVIDED FOR LAST VEHICLE VERIFICATION BETWEEN TGA & IBS AND INTERLOCKED WITH BLOCK INSTRUMENT OF BUJ W/PANEL IN DN. DIRECTION
 4. CONTROL INSTRUMENT OF TGA-BUJ W/PANEL IN UP DIRECTION
 5. CONTROL TELEPHONE PROVIDED AT PANEL CABIN
 6. MAGNETO TELEPHONE CONNECTED BETWEEN PANEL ROOM AND EAST & WEST LOCATION AND PANEL ROOM - L.C. GATE NO. 9SP/L: 10C: 11C: 12C: 13C: 14C: 15C: 16B & 17B.
 7. ADDITIONAL BOOM SLIDE LOCKING PROVIDED AT L.C. NO. 9SP/L: 14B: 15C & 16B:

| | | | | | | | |
|-----------------------------|--|-------------------------------------|--------------------|-------------------|--|-----------------------------|--|
| EAST CENTRAL RAILWAY | | STATION WORKING RULE DIAGRAM | | TEGHIRA | | SWRD NO. | |
| SONPUR DIVISION | | DST/E/CR/SEE | SSE/DRG/SEE | SE/DRG/SEE | TO SUIT S/P NO. ECR/SIP/SEE/162/209 | S/DST/SEE/2013/RD/23 | |
| | | MACL. STD-II(R) CLASS-'B' | | | | | |