

East Central Railway

Office of the  
General Manager/S&T  
Hajipur

No. ECR/S&T/Misc. (276077)

Dated 26/06/2024.

Sr.DSTE,  
DNR/DHN/DDU/SEE & SPJ,  
East Central Railway.

Sub:- Drive to check SOD Infringement because of Route Indicator.  
Ref:- This office letter of even No.. dated 10/04/2024.

In reference to above letter, the survey was done and the data received by the division has been analyzed in HQ. The analysis is tabulated below:

S.No.	Division	No. of Signals with Route indicator infringement
1.	DDU	48
2.	DHN	101
3.	DNR	65
4.	SEE	26
5.	SPJ	31
Total		271

Divisions are advised to ensure clearing these infringements by suitably replacing route indicator with a stencil/multi-lamp type route indicator. Progress of the same should be intimated through monthly MCDO to PCSTE.

राकेश रंजन  
26/06/24  
(राकेश रंजन)  
मुख्य सिगनल इंजीनियर-I

Copy to-

- Ch.OS/Signal – for MCDO compilation.

MISC