

FREIGHT MAINTENANCE ACTIVITIES

(A) Major Freight depots: Barwadih, Obra, Patherdih & Patratu

(A.1) Examination Yards:

| Yard | BRWD | OBRA | PEH | PTRU |
|------------------------|---|------------------|---------------------|--------------|
| Pattern of Examination | CC rakes (BOBRN) | CC rakes (BOBRN) | CC rakes (BOBRN) | -- |
| | BPC validity: 7500 Kms Or 30+5 days | | | |
| | Premium rakes | Premium rakes | Premium rakes | Premium rake |
| | BPC validity: 12+3 days | | | |
| | End to End | End to End | End to End | End to End |
| | BPC validity: Loading point to up to destination. | | | |
| | BOBRN Door checking | Post tipping | BOBRN Door checking | -- |

(A.2) Sick line sheds:

| Sick line/ROH | BRWD | OBRA | PEH | PTRU |
|---------------------|---|--|--|--|
| Sick line facility | Yes | Yes | Yes | Yes |
| ROH facility | Yes | -- | -- | -- |
| Category of repairs | General damage and A, B, C category repair, ROH, Trolley repair section, Wheel turning, CTRB mounting/dismounting, UST facility of axle, Overhauling section of Air brake system. | General damage and A, B, C category repair | General damage and A, B, C category repair | General damage and A, B, C category repair |

(B) Minor Freight depots: KDS, KTH, KQR, PUS, RAY, GHD, SKTN

| SN | C&W Activities | KDS | KTH | KQR | PUS | RAY | GHD | SKTN |
|----|---|-----|-----|-----|-----|-----|-----|------|
| 1. | BOBRN Door checking & repairing | Yes | Yes | -- | Yes | Yes | -- | Yes |
| 2. | Attention of en-route trouble shooting | Yes | Yes | Yes | Yes | Yes | Yes | Yes |
| 3. | Attention of critical & maintenance alarms received from WILD | -- | -- | -- | -- | -- | Yes | -- |

(C) Railway owned Weighbridges:

| SN | Station | Make | D.O.C. |
|----|-----------|-----------|------------|
| 1 | Latehar | PIPL | 14.12.2017 |
| 2 | Meralgram | PIPL | 28.12.2017 |
| 3 | Renukoot | Rice Lake | 26.11.2016 |
| 4 | SGRL | Rice Lake | 20.10.2016 |
| 5 | Chainpur | Rice Lake | 31.05.2017 |
| 6 | Dugda | Rice Lake | 21.08.2017 |
| 7 | Mahadiya | SPIL | 12.09.2014 |

| SN | Station | Make | D.O.C. |
|----|-------------|-------|------------|
| 8 | Barkakana | Essae | 25.05.2019 |
| 9 | Koderma | Essae | 14.08.2019 |
| 10 | Karela Road | Essae | 11.07.2019 |
| 11 | Chopan | Essae | 02.08.2019 |
| 12 | Gomoh-1 | Essae | 23.10.2019 |
| 13 | Gomoh-2 | Essae | 23.10.2019 |

(D) Position of Test Wagon/Dhanbad

| | | | |
|----|----------------------------|----|-------------------------|
| 1. | Test van no.BCNA-MI-107627 | 4. | Test van no.ER-50975 |
| 2. | Test van no.NR-91856 | 5. | Test van no.CR-60598 |
| 3. | Test van no.WR-983846 | 6. | Empty-wagon no.SR-42155 |

(E) Position of Test Wagon/Barwadih

| | | | |
|----|---------------------------|----|--------------------------------|
| 1. | Test van no.SE-BCN-106876 | 4. | Test van no.ER-BCN-51831 |
| 2. | Test van no.NF-BCN-36477 | 5. | Test van no.NR-BCN-92187 |
| 3. | Test van no.SF-BCN-130929 | 6. | Empty-wagon no.NR-BCNMI-110674 |

(F) Diesel Water Pumps for water supply: Total stations: 07

| | | | | | | |
|-----------|---------|----------------|---------|---------|-------------|-------------|
| Parasnath | Latehar | Mc Cluskieganj | Jogidih | Gurmura | Dudhi Nagar | Nagaruntari |
|-----------|---------|----------------|---------|---------|-------------|-------------|

(G) Wheel impact load Detector System (WILD):

| | |
|-----------------|--|
| Supplier | M/S- Apna Technologies & Solutions Ltd., Chennai |
| Location | Km 277/1-3 near Chianki (CNF) on up main line |
| AMC with O.E.M. | From 01/06/2019 to 31/05/2023. |

(H) Repair of unsuitable BOXN wagons at sidings:

- (i) 57 Wharf loading sidings through outsourcing of 20 Mobile Units
- (ii) West Bokaro Siding (TATA), Chainpur.