


# FREIGHT MAINTENANCE ACTIVITIES

## ORGANISATION CHART



(A) **Major Freight depots:** Barwadih, Obra, Patherdih & Patratu

(A.1) **Examination Yards:**

Yard	BRWD	OBRA	PEH	PTRU
Pattern of Examination	CC rakes (BOBRN)	CC rakes (BOBRN)	CC rakes (BOBRN)	CC rakes (BOXNHL) w.e.f. 02/02/2022
	BPC validity: 7500 Kms Or 30+5 days			
	Premium rakes	Premium rakes	Premium rakes	Premium rake
	BPC validity: 12+3 days			
	End to End	End to End	End to End	End to End
	BPC validity: Loading point to up to destination.			
	BOBRN Door checking	Post tipping	BOBRN Door checking	--

(A.2) **Sick line sheds:**

Sick line/ROH	BRWD	OBRA	PEH	PTRU
Sick line facility	Yes	Yes	Yes	Yes
ROH facility	Yes	--	--	--
Category of repairs	General damage and A, B, C category repair, ROH, Trolley repair section, Wheel turning, CTRB mounting/dismounting, UST facility of axle, Overhauling section of Air brake system.	General damage and A, B, C category repair	General damage and A, B, C category repair	General damage and A, B, C category repair

**(B) Minor Freight depots: KDS, KTH, KQR, PUS, RAY, GHD, SKTN**

SN	C&W Activities	KDS	KTH	KQR	PUS	RAY	GHD	SKTN
1.	BOBRN Door checking & repairing	Yes	Yes	--	Yes	Yes	--	Yes
2.	Attention of en-route trouble shooting	Yes	Yes	Yes	Yes	Yes	Yes	Yes
3.	Attention of critical & maintenance alarms received from WILD	--	--	--	--	--	Yes	--

**(C) Railway owned Weighbridges:**

SN	Station	Make	D.O.C.
1	Latehar	PIPL	14.12.2017
2	Meralgram	PIPL	28.12.2017
3	Renukoot	Rice Lake	26.11.2016
4	SGRL	Rice Lake	20.10.2016
5	Chainpur	Rice Lake	31.05.2017
6	Dugda	Rice Lake	21.08.2017
7	Mahadiya	SPIL	12.09.2014
8	Barkakana	Essae	25.05.2019

SN	Station	Make	D.O.C.
9	Koderma	Essae	14.08.2019
10	Karela Road	Essae	11.07.2019
11	Chopan	Essae	02.08.2019
12	Gomoh-1	Essae	23.10.2019
13	Gomoh-2	Essae	23.10.2019
14	Krishnashila	Essae	18.08.2021
15	Dhanbad	Essae	07/12/2021

**(D) Position of Test Wagon/Dhanbad**

1.	Test van no. BCN(M-1) 30079264799	4.	Test van no. BCN(M-1) 30079460542
2.	Test van no. BCN 30039063028	5.	Test van no. BCNA 30019360598
3.	Test van no. BCN 30089865887	6.	Empty-wagon no. BCNA 30019431069

**(E) Position of Test Wagon/Barwadih**

1.	Test van no.SE-BCN-106876	4.	Test van no.ER-BCN-51831
2.	Test van no.NF-BCN-36477	5.	Test van no.NR-BCN-92187
3.	Test van no.SF-BCN-130929	6.	Empty-wagon no.NR-BCNMI-110674

**(F) Diesel Water Pumps for water supply: Total stations: 07**

Parasnath	Latehar	Mc Cluskieganj	Jogidih	Gurmura	Dudhi Nagar	Nagaruntari
-----------	---------	----------------	---------	---------	-------------	-------------

**(G) Wheel impact load Detector System (WILD):**

Supplier	M/s Apna Technologies & Solutions Ltd., Chennai, D.O.C.: 18/04/2011
Location	Km 277/1-3 near Chianki (CNF) on up main line
AMC with O.E.M.	From 01/06/2019 to 31/05/2023.

**(H) Repair of unsuitable BOXN wagons at sidings:**

- (i) Outsourcing of 22 Mobile Units for 51 Wharf loading sidings,
- (ii) West Bokaro Siding (TATA), Chainpur.