


FREIGHT MAINTENANCE ACTIVITIES

ORGANISATION CHART



(A) **Major Freight depots:** Barwadih, Obra, Patherdih & Patratu

	PEH	PTRU	BRWD	OBRA
Type of examination	--	BOXN/HL based CC rakes BPC validity: 35+5 days or 10000 Kms.	BOBRN based CC rakes BPC validity: 30+5 days or 75000 Kms.	--
	Premium Examination	Premium Examination	Premium examination	Premium examination
	End to End examination	End to End examination	End to End examination	End to End examination
	BOBRN Door checking	--	BOBRN Door checking	BOXN Door checking/securing

(B) **Sick line sheds:**

Sick line/ROH	BRWD	OBRA	PEH	PTRU
Sick line facility	Yes	Yes	Yes	Yes
ROH facility	Yes	--	--	--
Category of repairs	General damage and A, B, C Cat. repair, ROH, Trolley repair section, Wheel turning, CTRB mounting/dismounting, UST facility of axle, Overhauling section of Air brake system.	General damage & A, B, C category repair	General damage & A, B, C category repair	General damage & A, B, C category repair

(C) Minor Freight depots: KDS, KTH, KQR, PUS, RAY, GHD, SKTN

SN	C&W Activities	KDS	KTH	KQR	PUS	RAY	GHD	SKTN
1.	BOBRN Door checking & repairing	Yes	Yes	--	Yes	Yes	--	Yes
2.	Attention of en-route trouble shooting	Yes	Yes	Yes	Yes	Yes	Yes	Yes
3.	Attention of critical & maintenance alarms received from WILD	--	--	--	--	--	Yes	--

(B) Railway owned Weighbridges:

SN	Station	Make	D.O.C.
1	Latehar	PIPL	14.12.2017
2	Meralgram	PIPL	28.12.2017
3	Renukoot	Rice Lake	26.11.2016
4	SGRL	Rice Lake	20.10.2016
5	Chainpur	Rice Lake	31.05.2017
6	Dugda	Rice Lake	21.08.2017
7	Mahadiya	SPIL	12.09.2014
8	Barkakana	Essae	25.05.2019

SN	Station	Make	D.O.C.
9	Koderma	Essae	14.08.2019
10	Karela Road	Essae	11.07.2019
11	Chopan	Essae	02.08.2019
12	Gomoh-1	Essae	23.10.2019
13	Gomoh-2	Essae	23.10.2019
14	Krishnashila	Essae	18.08.2021
15	Dhanbad	Essae	07/12/2021

(C) Position of FIO Test Van/Dhanbad

1.	Test van no. BCN(M-1) 30079264799	4.	Test van no. BCN(M-1) 30079460542
2.	Test van no. BCN 30039063028	5.	Test van no. BCNA 30019360598
3.	Test van no. BCN 30089865887	6.	Empty-wagon no. BCNA 30019431069

(D) Position of FIO Test Van/Barwadih

1.	Test van no.SE-BCN-106876	4.	Test van no.ER-BCN-51831
2.	Test van no.NF-BCN-36477	5.	Test van no.NR-BCN-92187
3.	Test van no.SE-BCN-130929	6.	Empty-wagon no.NR-BCNMI-110674

(E) Diesel Water Pumps for water supply: Total stations: 07

Name of Station:	Parasnath	Latehar	Mc Cluskieganj	Jogidih	Gurmura	Dudhi Nagar	Nagaruntari
No. of Pump:	2	2	2	2	1	2	2

(F) Wheel impact load Detector System (WILD):

Supplier	M/s Apna Technologies & Solutions Ltd., Chennai, D.O.C.: 18/04/2011
Location	Km 277/1-3 near Chianki (CNF) on up main line
AMC with O.E.M.	From 01/06/2019 to 31/05/2023.

(G) Repair of unsuitable BOXN wagons at sidings:

- (i) Outsourcing of 23 Mobile Units for 51 Wharf loading sidings,
- (ii) West Bokaro Siding (TATA), Chainpur.