

East Central Railway

No.SG.689/Pt-I

Dhanbad, dt. 30.09.24

SSE/SIG/1/&2/DHN,GMO & KQR
SSE/SIG/BRKA,BRWD & CPU
East Central Railway/DHN


Sub: Joint inspection of power supply for S&T installation at station/Cabin in Dhanbad division.

Ref:- i.Dy.CSO/HJP L No.ECR/Safety/Fire incidence/GAYA/DDU/24, dated 21.08.24
ii. JPO No. EL/2017.

In reference to above letter, JPO No. EL/2017 should be strictly followed by Supervisors of Signal & Electrical department. A Joint inspection by sectional signal and Electrical supervisors should be carried out for maintenance of power supply for S&T installation at station/cabin in every six months. But it is seen that JPO is not being followed by sectional Signal & Electrical supervisors.

Therefore, it is being instructed to Sectional supervisors(S&T and Electrical) that do joint inspection as per schedule and submit report to undersigned.

This is for your kind information and necessary action please.


Sr.DSTE(Co-ord)/DHN
E.C. Rly/Dhanbad

Copy to : Sr.DEE(G)/DHN –for kind information & n/a please.
All S&T Officers -for information & n/a please.